Monthly CURSORY INSPECTION

Parish:	Assumption		Str. Type: COSLAB				
Str.#	6104232	0104611	Recall #	051440	o o responsa e escapa de esta de escapa	Route:	LA 70
Bridge Name/Feature Crossed:			Bayou Choupique				
	Approaches: Roadway:	Marie					
Deck:		$\sqrt{-}$ If element of structure was inspected					
	Bearings:	The state of the s	•				
A1 8 1	Stringers:	1900 to the second seco	•	N/A - If e	lement do	es not apply	to structure
Girders	(Conc./Steel): Piling:						_{all} gepteterions _{to}
	Caps/Piers:		•	Were Pictu	ires Take	n: YES	or (NO)
	Backwalls:	<u> </u>					
	Wingwalls: Footings:	The second secon	•				
	Waterway:	resemble to the second	•				
Embank	ment (Scour):	WHITEHOUSE STATE OF THE PARTY O	•				
	Spall/Cracks:		•				
		NAMES OF THE PROPERTY OF THE P	Λ	الغاسات			/
Any char	iges noted? If	so what?	H Visual	Inspection	on wa	5 Dertoi	emed as well
as me	asure ments	taken or	i both s	ides of	the	structus	~ 11/14 a
<u>transit</u>	<u>level. Th</u>	ere were	no chang	es when	Com	oared i	o previous
inspec	<u>tions</u>		**	***************************************			
	ev recent control or in the control of the control	etri reversi di si di monte e e e e e e e e e e e e e e e e e e				NAME DATE OF THE PROPERTY OF THE PROPERTY OF THE PARTY OF	e Marier Hander Marie Balance Balance (Marie Balance) (Marie B
dame	nspected By: Date:	Brandon 11 3/30/16	lagruder o	+ Billy	BA	fantz	

Bayou Choupique

Date 3/30/16

TBM	10.0 ft
BS	2,16
HI	English of Marie Control of Marie Contro

Bent	No.	BS	Elev
1	L.	1,82	
	R	1.80	
2	L,	1.77	1
***************************************	R	1.76	
3	L.	1.72	
***************************************	R	1,74	
4	L	1,74	
9-70-70-80; CC CT (1/60-10) 100-10-10-10-10-10-10-10-10-10-10-10-10-	R	1.77	
5	L	1,79	
	R	1.80	